

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14716Main Street:BRIAR_CREK_RDCross Street:E_INDEPENDENCE/BRIAR_CREEK_RALocation:SWADA ID: C7282B8FE827Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Surface Condition? (G/P)

Good



Street 1 Name E INDEPENENCE /BRIAR CREEK RAMP
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

o/Possible Solution	Field Measurements/Component Compliance						
Possible Solutions:		Comp	liance Description	Data	Complia	nce Description	Data
Remove & Replace Entire F	Ramp.	N/A	Ramp Length (in)	54.0	Yes	Ramp Slope (%)	6.4
	•	No	Ramp Width (in)	39.0	Yes	Ramp XSlope (%)	1.0
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ř.		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
8		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
#		N/A	Shared Landing?	N/A			
PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To N		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
Total Cost:	\$ 1850.00		Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A





