

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.7

1.8

N/A

Good

Intersection ID: 46688 Main Street: NIGHTSHADE OAKS DR Cross Street: TROTTERS RIDGE RD Location: NE **Overall Compliance: No** 12.5 ADA ID: C72ED5EC99E1 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

48.0

48.0

N/A

No

To W

N/A

2.5

1.3

N/A

N/A

N/A

N/A

N/A



TROTTERS RIDGE RD Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	Compliance Description	
Remove & Replace Entire Ramp.	N/A Ramp Length (in)	
	Yes Ramp Width (in)	
	N/A Flare Type LT	
	N/A Flare Slope LT (%))
	N/A Flare Traversable	L٦
	N/A Landing Length (in)
Surveyor Notes:	N/A Landing Width (in)	
N/A	N/A Landing Slope (%)	
	N/A Landing X Slope (9	%
	N/A Landing Curb? (Y/	N)
	N/A Shared Landing?	
PROW/ADA:	N/A Gutter Ponding?	
Not Found, R304.2.2	N/A Gutter Lip Ht (in)	
	N/A Painted X Walk1?	
	X Walk 1 Direction	
	N/A X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope ((%
	N/A Ramp inside XWal	k1
	Road Slope (%)	

•			
N/A			N/A
			N/A
			N/A
			N/A
PROW/ADA:			N/A
Not Found, R304.2.2			N/A
ŕ			N/A
			N/A
			N/A
Total Cost:	\$	1850.00	N/A
iolai Cost.	Φ	1000.00	

N/A	Ramp Length (in)
Yes	Ramp Width (in)
N/A	Flare Type LT
N/A	Flare Slope LT (%)
N/A	Flare Traversable LT?
N/A	Landing Length (in)
N/A	Landing Width (in)
N/A	Landing Slope (%)
N/A	Landing X Slope (%)
N/A	Landing Curb? (Y/N)
N/A	Shared Landing?
N/A	Gutter Ponding?
N/A	Gutter Lip Ht (in)
N/A	Painted X Walk1?
	X Walk 1 Direction
N/A	X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (%)
N/A	Ramp inside XWalk1?
	Road Slope (%)
	Road X Slope (%)
N/A	Any Obstructions?



Obstruction Type



