

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10017066 Main Street: NEAL_RD **Cross Street: N/A** Location: S **Overall Compliance: No** ADA ID: C7480E06E5BC Ramp Type: PerpDiag Initial Pass/Fail: Fail **Severity Score:** 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.2.2, R304.5.3

	12-1
treet 1 Name	ENTRANCE
top Condition-Street 2	None
treet 2 Name	NEAL RD
top Condition-Street 1	None

Total Cost: 3200.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	97.0	No	Ramp	Slope (%)	10.8
Yes	Ramp Width (in)	57.0	No	Ramp	XSlope (%)	6.2
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Walk 1 Direction	To NE		X Wa	lk 2 Direction	To NW
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.2		X Wa	lk 2 Slope (%)	6.7
	X Walk 1 X Slope (%)	6.8		X Wa	lk 2 X Slope (%)	0.5
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	5.7	N/A	Clear	Space?	N/A
	Road X Slope (%)	6.7	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A

Surface Condition? (G/P)

Good





