

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27530 Main Street: BALLANTYNE_COMMONS_PY Cross Street: BALLANTYNE_FOREST_DR Location:									NW
ADA ID: C790518E43AE Ramp Type: Perp			initiai	Initial Pass/Fail: Fail Overall Compliance: No					1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
ない	HE SU	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Entire Ram	ıp.	N/A	Ramp Length (in)	107.0	Yes	Ramp Slope (%)	5.7
- 18 MA				Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	2.1
15.2 100				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
- A. P.				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A MARINE				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	a da	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Carlos Carlos 1	E.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
AND THE REAL PROPERTY OF			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
MALE IN				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second second	6		N/A	Shared Landing?	N/A				
BALLANU	1. 1. 20	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and the second s	6	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the state of the s				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BALLANTYNE FOREST DR				X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							1		

s Surface Condition? (G/P)

Good

