cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44936	Main Str	Main Street: REEDMONT_LN			Cross Street: ACORN FOREST LN				w
ADA ID: C7E88DF9E6FD		Ramp Type: PerpDiag					Location: o Severity Score:		
			millari	Initial Pass/Fail: Fail Overall Compliance: No					0.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Da			a Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.5
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.0
20 min-l		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
REEDMON				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ACUT LIN	ALLAN .			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	E.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
1 1 2 2 1 1 1	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Mr. Car	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ACORN FOREST LN	•			X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	1.5
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	0.6
Street 2 Name	REEDMONT LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	0.0 N/A
Stop Condition-Street 1	StopSign			11/4	Road Slope (%)	2.6	N/A	Clear Space?	N/A
	StopSign								
				NI/A	Road X Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A
		T-1-1-0		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P) Good

