cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·									
Intersection ID: 17353	Main Street: JAMESTON_DR			Street:	LYNNWOOD_DR	Location:	NE		
ADA ID: C8108240D1D2	Ramp Ty	Ramp Type: PerpDiag			ail: Fail Overall C	o Severity Score:	22.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp \	With	N/A	Ramp Length (in)	68.0	No	Ramp Slope (%)	9.6
		Two New Directional Ramps or		No	Ramp Width (in)	37.0	No	Ramp XSlope (%)	2.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
EU CAR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E E		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
LTMINWOOD				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
G G				N/A	Shared Landing?	N/A			
The second second	Contraction of the second	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	FORM & M	Not Found, R304.5.1, R304.2.2 R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To W		X Walk 2 Direction	To S	
The first of the second				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	JAMESTON DR				X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	0.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	1.4
Street 2 Name	LYNNWOOD DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.7	N/A	Clear Space?	N/A
					Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

