


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9409	Main Street: THRIFTWOOD_DR	Cross Street: N/A	Location: S
ADA ID: C8222DA4AEF5	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 10	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	Compliance
	Remove & Replace Entire Ramp.		Yes	Ramp Length (in)	56.0	Description
			No	Ramp Width (in)	47.5	Ramp XSlope (%)
			N/A	Flare Type LT	N/A	Flare Type RT
			N/A	Flare Slope LT (%)	N/A	Flare Slope RT (%)
			N/A	Flare Traversable LT?	N/A	Flare Traversable RT?
			N/A	Landing Length (in)	N/A	DWS Provided?
			N/A	Landing Width (in)	N/A	DWS Contrast?
			N/A	Landing Slope (%)	N/A	DWS Length (in)
			N/A	Landing X Slope (%)	N/A	DWS Full Width?
			N/A	Landing Curb? (Y/N)	N/A	DWS Offset (in)
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	Gutter Slope (%)
			N/A	Gutter Lip Ht (in)	N/A	Gutter X Slope (%)
			N/A	Painted X Walk1?	No	Painted X Walk2?
				X Walk 1 Direction	To NE	X Walk 2 Direction
			N/A	X Walk 1 Width (in)	N/A	X Walk 2 Width (in)
				X Walk 1 Slope (%)	1.0	X Walk 2 Slope (%)
				X Walk 1 X Slope (%)	2.6	X Walk 2 X Slope (%)
			N/A	Ramp inside XWalk1?	N/A	Ramp inside XWalk2?
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.5.3</p>			N/A	Road Slope (%)	N/A	Clear Space?
			N/A	Road X Slope (%)	N/A	Clear Space to XWalk (in)
			N/A	Any Obstructions?	N/A	Storm Grate/Utility Hazard?
				Obstruction Type		Storm Grate/Utility Type
			N/A			
			N/A			
			Yes	Surface Condition? (G/P)		Good

Total Cost: \$ 1850.00

