

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6634 Main Street: ABERGLEN DR Cross Street: DOVERHILL PL Location: NE **ADA ID: C84D0EF5747D** Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **ABERGLEN DR** None **DOVERHILL PL** StopSign Possible Solutions: **Remove & Replace Curb Ramp With Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2

Total Cost: 3200.00

Field Measurements/Component Compliance						
Com	Compliance Description		Compliance		Description	Data
N/A	Ramp Length (in)	47.0	No	Ram	Slope (%)	8.8
No	Ramp Width (in)	47.0	Yes	Ram	XSlope (%)	0.5
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	1.0	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To W		X Wa	lk 2 Direction	To S
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.6		X Wa	lk 2 Slope (%)	0.1
	X Walk 1 X Slope (%)	0.5		X Wa	lk 2 X Slope (%)	4.9
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	2.9	N/A	Clear	Space?	N/A
	Road X Slope (%)	5.0	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good
1	33.4					





