

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A

7.1

2.1

N/A

No

N/A

3.4

3.9

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 8.9

To SE

Intersection ID: 22211 Main Street: SHARON_VIEW_RD Cross Street: VAUXHALL_CT Location: N

ADA ID: C85E57ACDF22 Ramp Type: Combination2Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

None SHARON VIEW RD StopSign VAUXHALL CT Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.


Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.1, R304.5.3, R304.3.2

Total Cost: \$ 3200.00



6.6

N/A

5.5

0.8

N/A

N/A

N/A

N/A

Yes

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)







N/A