

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

14.1

3.1

Intersection ID: 44919 Main Street: PALUSTRIS CT **Cross Street: MINTVALE_DR** Location: NW **Overall Compliance: No** ADA ID: C8D3C5C98CB6 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

46.0 No

48.0 No

Data Compliance Description

Ramp Slope (%)

Ramp XSlope (%)



i ossible solution		i ieiu ivie
Possible Solutions:	Compl	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	Yes	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%)
	N/A	Landing Curb? (Y/N)
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
Not Found, R304.2.2, R304.5.3	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk1
		Road Slope (%)





A STATE OF THE PARTY OF THE PAR	STREET, STREET								
M. A. Marine and M. M. M.	A Sharm			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Make M			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	1 6 W	Surveyor Notes:			Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
PALUS <mark>TRIS_C</mark>	E & /	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Carineouric	(C) [N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E C ETVANIANIM	5			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	San Parkey			N/A	Shared Landing?	N/A			
	TINA IIIIA	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1000	Not Found, R304.2.2, R304.5.	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1	, ,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	Townson, St.			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PALUSTRIS CT				X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good
			1. 10						