


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 45154	Main Street: REID_OAKS_DR	Cross Street: MAGNASCO_LN	Location: SE
ADA ID: C92B5E2D468C	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 18.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
<div></div> <div>Street 1 NameMAGNASCO LNMagnasco Ln</div> <div>Stop Condition-Street 2StopSign</div> <div>Street 2 NameREID OAKS DRReid Oaks Dr</div> <div>Stop Condition-Street 1None</div> <div>Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.</div> <div>Surveyor Notes: N/A</div> <div>PROW/ADA: R304.5.1, R304.5.3</div> <div>Total Cost:\$ 3200.00</div>			Compliance	Description	Data	Compliance	Description	Data
			N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	7.7
			No	Ramp Width (in)	35.5	No	Ramp XSlope (%)	3.4
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To N		X Walk 2 Direction	To W
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	6.1		X Walk 2 Slope (%)	2.8
				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	6.8
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	2.0	N/A	Clear Space?	N/A			
	Road X Slope (%)	5.1	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			

