

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



						Leastien			
Intersection ID: 6640	Main Street: ARVIN_DR			eet:	COCHRANE_DR	Location:	NE		
ADA ID: C92C1ABA6801	A6801 Ramp Type: Perp			s/Fa	ail: Fail Overall C	o Severity Score:	21.25		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description Data Complia			liance Description	Data		
3111111		Remove & Replace Entire Ramp	. N/	/ <b>A</b>	Ramp Length (in)	95.0	No	Ramp Slope (%)	8.5
	A De min		N	0	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	0.0
HILL IN A COMP	AN ALL		N/	/ <b>A</b>	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	A CONTRACT		N	/ <b>A</b>	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	When The		N	/ <b>A</b>	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Real Van		N	/ <b>A</b>	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:	N	/ <b>A</b>	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A	N	/ <b>A</b>	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	A DE		N	/ <b>A</b>	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the the terms	State		N	/ <b>A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6	- Pro-		N	/ <b>A</b>	Shared Landing?	N/A			
GOOHRANE DR &	1	PROW/ADA:	N	/ <b>A</b>	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
the state	and and	Not Found, R304.5.1, R304.2.2	N/	/ <b>A</b>	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
La	10 M		N	/ <b>A</b>	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
	N. A. W		N	/ <b>A</b>	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name S1	TATESVILLE RD				X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N	/ <b>A</b>	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N	/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

