

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.0

2.2

N/A

No

N/A

1.4

2.8

N/A

N/A

N/A

N/A

N/A

Good

To NE

Intersection ID: 48196 Main Street: BLAKENEY_PARK_DR Cross Street: REA_RD Location: W

ADA ID: C957723D3484 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

42.0

N/A

Yes



Street 1 Name REA RD
Stop Condition-Street 2 None
Street 2 Name BLAKENEY PARK DR
Stop Condition-Street 1 StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

No No Ramp Width (in) 45.5 N/A N/A Flare Type LT N/A N/A N/A N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A N/A N/A N/A Landing Length (in) N/A Landing Width (in) N/A N/A N/A N/A N/A Landing Slope (%) N/A Landing X Slope (%) N/A N/A N/A Landing Curb? (Y/N) N/A N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A N/A Gutter Lip Ht (in) N/A N/A N/A Painted X Walk1? No N/A X Walk 1 Direction To SE N/A N/A N/A X Walk 1 Width (in) X Walk 1 Slope (%) 3.2 X Walk 1 X Slope (%) 1.6 N/A N/A N/A Ramp inside XWalk1? Road Slope (%) 2.0 N/A N/A Road X Slope (%) 2.3 N/A N/A N/A Any Obstructions? **Obstruction Type**

Compliance Description

Ramp Length (in)

N/A





Total Cost:



3200.00