

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Internection ID: 7702 Main Street: IEEE ADAMS DD						Location	C)M			
Intersection ID: 7793	ction ID: 7793 Main Street: JEFF_ADAMS_DR			reet:	STATESVILLE_AV	Location:	SW			
ADA ID: C95842C3BAF1 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Jana Par	Possible Solutions:		Compliance Description			Data Compliance Description			
	- N. Weiner	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.7	
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.3	
	G.E.		I	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
G L L L				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	HER ADAMS PA			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
TIPTON_DR	STATES			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A Statistic		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	ER - +			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
6				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
a let de la				N/A	Shared Landing?	N/A				
English Contact		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	(E)	Not Found, R304.2.2, R304.5.3	1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	IE			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
	t. 14			N/A	X Walk 1 Width (in)	99.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	TIPTON DR				X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

