## cole

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



N/A

Good

20.0

Surface Condition? (G/P)

Curb Slope (%)

Yes

Intersection ID: 8925	Main Street: E_W_T_HARRIS_BV				Cross Street: THE_PLAZA				Location:	SW	
ADA ID: C976DA4D9821	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Complianc				o Severity Score:	35	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description		Data Compliance Description			Data	
	-	Remove & Replace	Entire Rai	np.	N/A	Ramp Length LT (in)	50.0	N/A	Ramp Length RT (in)	54.0	
	NAME 7	·		•	No	Ramp Width LT (in)	45.5	No	Ramp Width RT (in)	46.0	
15 1 G.	1.8.14				No	Ramp Slope LT (%)	14.7	Yes	Ramp Slope RT (%)	2.3	
6.					No	Ramp XSlope LT (%)	3.8	No	Ramp XSlope RT (%)	3.1	
Store Shutt	IS IIIIII.				N/A	Ramp Length (in)	26.0	Yes	Ramp Slope (%)	2.5	
3/00/ 8	A CHARACTER AND A CHARACTER ANTACTER ANTACTER ANTACTER ANTACTER ANTACTER ANTAC				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.5	
Pril - E		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
5/12 E		DAMAGED DWS, RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	" E				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	dan a fre	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		Not Found, R304.5.	1, R304.5.	3,	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	1111	R304.3.2			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	YieldSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	THE PLAZA				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	110.5		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		E	12500	A 104 4	. 14.	inter litter		N/A	Any Obstruction?	N/A	
									Obstruction Type		
					000					N/A	
		1/2-		and the second state of th	The second	and the second sec		N/A	Storm Grate/Utility Hazard?	N/A	
X Y IS	17			/	for an an				Storm Grate/Utility Type		

