## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25628 Main Street: WINDSWEPT_DR				Cross Street: PINEVILLE-MATTHEWS_RD					Location:	NE
					Initial Pass/Fail: Pass Overall Compliance: No					
ADA ID: C990F4F1A576 Ramp Type: Perp			initial	Pass/Fa			12.75			
	/Possible Solution	e Solution Field Measurements/Compone								
		Possible Solutions:			Compliance Description		Data Compliance Description			Data
A Map 21		Remove & Replace En	tire Ram	р.	N/A	Ramp Length (in)	84.0	Yes	Ramp Slope (%)	7.8
3.14					Yes	Ramp Width (in)	52.0	No	Ramp XSlope (%)	4.7
A CONTRACT OF					N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
	SI / A / A SA				N/A	Flare Slope LT (%)	8.8	Yes	Flare Slope RT (%)	8.5
A CALLER AND					N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
MARCO SH	1 A MAR CAR				No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
TEN RELEVE	(1. 19) Sare 1 19	Surveyor Notes:			No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
203 ×		N/A			No	Landing Slope (%)	N/A	Yes	DWS Length (in)	29.0
	6. )				No	Landing X Slope (%)	N/A	No	DWS Full Width?	No
	NA CONTRACT				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	6.5
	Part and				N/A	Shared Landing?	No			
A A A A A A A A A A A A A A A A A A A		PROW/ADA:			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.6
	TO NA VILLE	R304.5.3, R304.2.1, R3	04.2.2-Pe	erp,	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.6
A BE LANKEN		R304.3.2-Para, R305.1.			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
1111 Same	CARLAN A LARGE					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
11 1 1 1 23					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PINEVILLE-MATTHEWS RD					X Walk 1 Slope (%)	5.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	Yes
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A
								Yes	Surface Condition? (G/P)	Good

