

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 7131	Main Street: N_TRYON_ST	Cross Street: ORCHARD_TRACE_LN	Location: NW
ADA ID: C995D0DFFDA1	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 5	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Detectable Warning System. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

R305.2, R304.5.4

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	123.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	97.0	Yes	Grade Break Slope (%)	2.0
Yes	Ramp Slope (%)	7.3	Yes	Grade Break XSlope (%)	1.8
Yes	Ramp XSlope (%)	1.2			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	74.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	97.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.2	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.4	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	No	DWS Offset LT (in)	17.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	28.0
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	6.3
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.0
N/A	Painted X Walk1?	Yes		Road Slope (%)	2.8
	X Walk 1 Direction	To E		Road X Slope (%)	1.1
	X Walk 1 Width (in)	105.0		Clear Space?	Yes
	X Walk 1 Slope (%)	2.8	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.1	Yes	Storm Grate/Utility Hazard?	No
Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	0.1

Total Cost: \$ 1550.00

