

Access Compliance Report Public Rights-of-Way (Curb Ramps)



 Intersection ID: N/A
 Main Street:
 MARKLAND_DR
 Cross Street:
 DENVIEW_LN
 Location:
 NE

 ADA ID: C9E4508E23E8
 Ramp Type:
 PerpDiag
 Initial Pass/Fail:
 Pass
 Overall Compliance:
 No
 Severity Score:
 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

MARKLAND DR None DENVIEW LN StopSign

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
	Compliance Description		Data	Compliance Description		Data
	N/A	Ramp Length (in)	73.0	Yes	Ramp Slope (%)	5.3
	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.7
	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	0.8	N/A	Flare Slope RT (%)	4.7
	N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
	Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
	Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
	Yes	Landing Slope (%)	1.7	Yes	DWS Length (in)	24.0
	Yes	Landing X Slope (%)	1.0	Yes	DWS Full Width?	Yes
	N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	6.0
	N/A	Shared Landing?	No			
	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.9
	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.6
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To W		X Walk 2 Direction	To S
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	3.9
		X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	2.5
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	2.6	N/A	Clear Space?	Yes
		Road X Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
	Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good





