

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16696 Main Street: COUNTRY OAKS RD **Cross Street: EWT HARRIS BV** Location: Ε ADA ID: C9E7BAB00AC0 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 25

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

EWTHARRISBV None **COUNTRY OAKS RD** StopSign Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.5.3

Total Cost: 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Data	
	N/A	Ramp Length (in)	58.0	No	Ramp	Slope (%)	9.3
	Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	6.6
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
		X Walk 1 Direction	To NW		X Wa	lk 2 Direction	To SW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
		X Walk 1 Slope (%)	2.3		X Wa	lk 2 Slope (%)	2.3
		X Walk 1 X Slope (%)	0.8		X Wa	lk 2 X Slope (%)	5.2
	N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
		Road Slope (%)	3.7	N/A	Clear	Space?	N/A
		Road X Slope (%)	3.0	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
		Obstruction Type			Storn	n Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ce Condition? (G/P)	Good
	1						





