


Intersection ID: 19457	Main Street: S_TRYON_ST	Cross Street: YORKDALE_DR	Location:	NE
ADA ID: C9EAB091A719	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 33.75

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance								
	Possible Solutions:	Compliance		Description		Data	Compliance	Description		Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	N/A	Ramp Length (in)	91.0	No	Ramp Slope (%)	9.0			
		No	Ramp Width (in)	39.0	No	Ramp XSlope (%)	6.1			
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
	Surveyor Notes:	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A		Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
PROW/ADA:	N/A	Shared Landing?	N/A							
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No				
		X Walk 1 Direction	To W		X Walk 2 Direction	To S				
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A				
		X Walk 1 Slope (%)	8.0		X Walk 2 Slope (%)	1.4				
		X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	8.3				
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A				
		Road Slope (%)	5.4	N/A	Clear Space?	N/A				
		Road X Slope (%)	7.3	N/A	Clear Space to XWalk (in)	N/A				
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
		Obstruction Type			Storm Grate/Utility Type					
			N/A			N/A				
Total Cost:		\$	3200.00	Yes	Surface Condition? (G/P)	Good				
Street 1 Name		S TRYON ST								
Stop Condition-Street 2		None								
Street 2 Name		YORKDALE DR								
Stop Condition-Street 1		StopSign								

