cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: N/A Mair	Main Street: LAWTON BLUFF RD		Cross Street: CANDLEWYCK_LN			Location:	NE	
ADA ID: C9F8381AE29A Ram	A Ramp Type: PerpDiag		nitial Pass/Fail: Fail Overall Compliance			Severity Score:	10	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Co	Compliance Description Data					
CONTROL FLUEFE RD	Remove & Replace Curb Ramp W				Yes	Ramp Slope (%)	5.1	
	Two New Directional Ramps or	No		,	No	Ramp XSlope (%)	2.3	
	Equivalent.	N/A	Flare Type LT	, N/A	N/A	Flare Type RT	N/A	
		N//	Flare Slope LT	(%) N/A	N/A	Flare Slope RT (%)	N/A	
		N//	Flare Traversat	ble LT? N/A	N/A	Flare Traversable RT?	N/A	
		N//	Landing Length	(in) N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N//	Landing Width	(in) N/A	N/A	DWS Contrast?	N/A	
	N/A	N//	Landing Slope	(%) N/A	N/A	DWS Length (in)	N/A	
		N//	Landing X Slop	e (%) N/A	N/A	DWS Full Width?	N/A	
		N//	• •		N/A	DWS Offset (in)	N/A	
		N//	A Shared Landing					
	PROW/ADA:	N//	-	-	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (ir	n) N/A	N/A	Gutter X Slope (%)	N/A	
		N//			N/A	Painted X Walk2?	No	
			X Walk 1 Direct	tion To W		X Walk 2 Direction	To S	
	de la	N//	X Walk 1 Width	(in) N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name CANDLEWYCK	LN		X Walk 1 Slope	(%) 1.3		X Walk 2 Slope (%)	0.9	
Stop Condition-Street 2 No.	ne		X Walk 1 X Slop	pe (%) 1.0		X Walk 2 X Slope (%)	1.8	
Street 2 Name LAWTON BLUFF	RD	N//	A Ramp inside XV	Nalk1? N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 StopS	gn		Road Slope (%)) 1.8	N/A	Clear Space?	N/A	
			Road X Slope (%) 2.1	N/A	Clear Space to XWalk (in)	N/A	
		N//	A Any Obstruction	ns? N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	00.00	Obstruction Typ	be		Storm Grate/Utility Type		
				N/A			N/A	