

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12925	Main Str	Main Street: S_CHURCH_ST			Cross Street: W_CARSON_BV				Location:	NW	
ADA ID: C9FDF3B2F996	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	26.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
A MARINE A MARINE	and the	Possible Solutions:			Compliance Description		Data Compliance Description		Data		
	115	Remove & Replace E	e Entire Ramp.		N/A	Ramp Length LT (in)	73.5		Ramp Length RT (in)	N/A	
I Charles					Yes	Ramp Width LT (in)	99.0	N/A	Ramp Width RT (in)	N/A	
	CAN A CAR				No	Ramp Slope LT (%)	12.2	N/A	Ramp Slope RT (%)	N/A	
	S. Andrew				Yes	Ramp XSlope LT (%)	0.8	N/A	Ramp XSlope RT (%)	N/A	
	No de				N/A	Ramp Length (in)	26.0	Yes	Ramp Slope (%)	6.0	
	L.				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.6	
	281 70	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		COMBO2 DIAG			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Te man	5				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
S. OILUIS	TUNE I	4			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
A ALLAN	1 BIC B	Not Found, R304.3.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
Contraction of the second seco	1 81 0				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	I FLI				N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	W CARSON BV				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	115.0		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
								N/A	Any Obstruction?	N/A	
									Obstruction Type	N/A	

- N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A
- Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 9.5





