

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10038782 Main Street: STEELE CREEK RD **Cross Street: N/A** Location: NW **Overall Compliance: No ADA ID: CA147D00A6D0** Ramp Type: PerpDiag Initial Pass/Fail: Fail **Severity Score:** 12.5

**Codes/Mitigation Info/Possible Solution** 

**ENTRANCE** 

STEELE CREEK RD

StopSign

None

## Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **Remove & Replace Curb Ramp With Two New Directional Ramps or** Equivalent.

Surveyor N N/A

PROW/AD

Not For

	IN/A
	N/A
	N/A
	N/A
Notes:	N/A
	N/A
	N/A
	N/A
	N/A
A:	N/A
und, R304.2.2	N/A
	N/A
	N/A
	N/J
	N/A

Total Cost: 3200.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	94.0	No	Ramp	Slope (%)	8.9
Yes	Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	0.4
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	To SE
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.1		X Wa	lk 2 Slope (%)	2.4
	X Walk 1 X Slope (%)	2.0		X Wa	lk 2 X Slope (%)	0.2
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	2.8	N/A	Clear	Space?	N/A
	Road X Slope (%)	0.1	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





