


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 14648	Main Street: EAST_BV	Cross Street: LENNOX_AV	Location: E
ADA ID: CA2B8EBFA783	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 15.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

**Remove & Replace Entire Ramp.  
Grind Gutter Lip.**

Surveyor Notes:

**LNDG SLOPE NEGATIVE, GTR GAP  
18.0"**

PROW/ADA:

**R304.5.3, R304.2.2-Perp, R304.3.2-  
Para, R302.7.2**

Total Cost: \$ 1800.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	69.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	72.0	Yes	Grade Break Slope (%)	2.5
Yes	Ramp Slope (%)	3.9	Yes	Grade Break XSlope (%)	1.7
No	Ramp XSlope (%)	2.2			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	54.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	72.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	7.8	Yes	DWS Length (in)	25.0
Yes	Landing X Slope (%)	0.2	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	0.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	26.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.0
No	Gutter Lip Ht (in)	3.0	Yes	Gutter X Slope (%)	1.1
N/A	Painted X Walk1?	No		Road Slope (%)	3.7
	X Walk 1 Direction	To SW		Road X Slope (%)	1.0
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.0	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	3.4

