

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 24796	Main Street: CHATHAM_OAKS_TL	Cross Street: PARK_CROSSING_DR	Location: SW
ADA ID: CA413A7987DF	Ramp Type: BlendTrans2	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 2.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		N/A	Ramp Length (in)	33.0	Yes	BlendTrans Slope (%)	1.8
			Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.3
			N/A	Flare Type LT	None	N/A	Flare Type RT	None
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
			N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
			N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
			N/A	Landing X Slope (%)	N/A	No	DWS Full Width?	No
Surveyor Notes: ASP LIP 0.5 PROW/ADA: R304.5.3, R305.1.4			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.0
			N/A	Shared Landing?	No			
			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.4
			Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.4
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To E		X Walk 2 Direction	To N
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	7.6
				X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	2.4
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	2.5		Clear Space?	Yes	
			Road X Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
			Obstruction Type			Storm Grate/Utility Type		
					N/A		N/A	
					Yes	Surface Condition? (G/P)	Good	
					N/A	Curb Slope (%)	4.8	

