

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interpretion ID: 0025 Main Street, TENNVSCH, DD					roct		Location	c		
Intersection ID: 9925				Cross Street: TUCKASEEGEE_RD					Location:	S
ADA ID: CA7E45155350 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	10	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Y, 1000	Possible Solutions:			Compl	iance Description	Data	Comp	liance Description	Data
	Pige F 1	Remove & Replace Entire	Ramp.		N/A	Ramp Length (in)	75.0	Yes	Ramp Slope (%)	7.8
	S. Main		•		No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	2.4
and the second s	A Page 1			I	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
LA L	A MA				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A CONTRACT OF		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second second	The Art of the	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A I MEN					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	E Stan				N/A	Shared Landing?	N/A			
	The states	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R30	)4.5.3	I	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	Real Street					X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	A BEALT				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name TL	JCKASEEGEE RD	_				X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good





