

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18461 Main Street: SHARON\_FOREST\_DR Cross Street: WALLACE\_RD Location: E

ADA ID: CA9BA36B3B38 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

SHARON FOREST DR StopSign WALLACE RD None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

ried Measurements/Component Comphance							
	Compliance Description		Data	Comp	liance Desc	Description	
	N/A	Ramp Length (in)	74.0	No	Ramp Slop	e (%)	8.9
	Yes	Ramp Width (in)	48.0	No	Ramp XSIo	pe (%)	3.8
	N/A	Flare Type LT	N/A	N/A	Flare Type	RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope	e RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Trave	ersable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provi	ded?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contr	rast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Leng	th (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full V	Vidth?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offse	t (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slop	oe (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X SI	ope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X \	Nalk2?	No
		X Walk 1 Direction	To NW		X Walk 2 D	irection	To SW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 W	/idth (in)	N/A
		X Walk 1 Slope (%)	5.8		X Walk 2 S	lope (%)	7.2
		X Walk 1 X Slope (%)	6.5		X Walk 2 X	Slope (%)	4.2
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp insid	le XWalk2?	N/A
		Road Slope (%)	4.2	N/A	Clear Spac	e?	N/A
		Road X Slope (%)	7.7	N/A	Clear Spac	e to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grat	e/Utility Hazard?	N/A

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







**Obstruction Type**