

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 16020 Main Street: MONROE\_RD **Cross Street: COMMONWEALTH AV** Location: NE ADA ID: CA9E9FB53D53 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 8.75

**Codes/Mitigation Info/Possible Solution** 



**COMMONWEALTH AV** Street 1 Name Stop Condition-Street 2 Signal Street 2 Name MONROE RD Stop Condition-Street 1 Signal

Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or Equivalent. Restripe Crosswalk.** Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

Total Cost: 3400.00

Field Measurements/Component Compliance					
Compliance Description Date		Data	Comp	liance Description	Data
N/A	Ramp Length (in)	149.0	Yes	Ramp Slope (%)	6.3
No	Ramp Width (in)	37.0	Yes	Ramp XSlope (%)	0.4
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To W		X Walk 2 Direction	To S
N/A	X Walk 1 Width (in)	115.0	N/A	X Walk 2 Width (in)	77.0
	X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	3.0
	X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	0.8
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	No
	Road Slope (%)	1.6	N/A	Clear Space?	N/A
	Road X Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
7	119				





