


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10039540	Main Street: THERMAL_RD	Cross Street: N/A	Location: SW
ADA ID: CAC0AEC01268	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 33.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance																			
	Possible Solutions:		Compliance			Description			Data		Compliance			Description			Data					
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		55.0		N/A	Grade Break?		N/A		N/A	Grade Break Slope (%)		0.0		N/A	Grade Break XSlope (%)		0.0	
			No	Ramp Width (in)		47.5		N/A	Grade Break Slope (%)		0.0		N/A	Grade Break XSlope (%)		0.0						
			Yes	Ramp Slope (%)		2.6		N/A	Grade Break XSlope (%)		0.0											
			No	Ramp XSlope (%)		8.1																
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A											
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		0.0											
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A											
			N/A	Landing Length (in)		0.0		N/A	DWS Provided?		N/A											
			N/A	Landing Width (in)		0.0		N/A	DWS Contrast?		N/A											
			N/A	Landing Slope (%)		0.0		N/A	DWS Length (in)		N/A											
			N/A	Landing X Slope (%)		0.0		N/A	DWS Full Width?		N/A											
			N/A	Landing Curb? (Y/N)		N/A		N/A	DWS Offset LT (in)		N/A											
			N/A	Shared Landing?		N/A		N/A	DWS Offset RT (in)		N/A											
			N/A	Gutter Ponding?		0.0		N/A	Gutter Slope (%)		N/A											
			N/A	Gutter Lip Ht (in)		0.0		N/A	Gutter X Slope (%)		N/A											
			N/A	Painted X Walk1?		No		Road Slope (%)		2.3												
				X Walk 1 Direction		To NW		Road X Slope (%)		6.0												
				X Walk 1 Width (in)		N/A		Clear Space?		N/A												
				X Walk 1 Slope (%)		2.3		N/A	Clear Space to XWalk (in)		N/A											
				X Walk 1 X Slope (%)		6.0		N/A	Storm Grate/Utility Hazard?		N/A											
			N/A	Ramp inside XWalk1?		N/A		Storm Grate/Utility Type														
			N/A	Any Obstructions?		N/A				N/A												
				Obstruction Type				Yes	Surface Condition? (G/P)		Good											
								N/A	Curb Slope (%)		6.8											
		Surveyor Notes:																				
		ASP LIP 1.0", CURB LIP 0.5"																				
		PROW/ADA:																				
		R304.5.1, R304.5.3																				
		Total Cost:		\$	1600.00																	

Street 1 Name	ENTRANCE
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

