


## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48069Main Street:ELLIOTT\_STCross Street:FERRELL\_AVLocation:NEADA ID: CB040FEBA9E7Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:8.75

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



	CONTROL OF THE RESIDENCE OF THE PARTY OF THE
Street 1 Name	FERRELL AV
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solution	
Possible Solutions:	Co
Remove & Replace Entire Ramp.	
•	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.1	N/A
·	N/A
	N/A
	N/A

Total Cost:



1850.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	50.0	Yes	Ramp	Slope (%)	7.4
No	Ramp Width (in)	46.5	Yes	Ramp	XSlope (%)	2.0
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To W		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.9		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.9		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good
- Make	WOLKE					