


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

| | | | |
|---|----------------------------|---|------------------------|
| Intersection ID: 20718 | Main Street: PROVIDENCE_RD | Cross Street: EAST_BARDEN_RD | Location: W |
| ADA ID: CB25CC46C600 | Ramp Type: PerpDiag | Initial Pass/Fail: Fail | Overall Compliance: No |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | |

| | | | | | | | |
|--|--|------------|-----------------------|-------|------------|-----------------------------|-------|
|  | Possible Solutions: | | | | | | |
| | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | | | | | | |
| | Surveyor Notes: | | | | | | |
| | N/A | | | | | | |
| | PROW/ADA: | | | | | | |
| | R304.2.2, R304.5.3 | | | | | | |
| Street 1 Name | WAST BARDEN RD | Compliance | Description | Data | Compliance | Description | Data |
| Stop Condition-Street 2 | StopSign | N/A | Ramp Length (in) | 58.0 | No | Ramp Slope (%) | 8.6 |
| Street 2 Name | PROVIDENCE RD | Yes | Ramp Width (in) | 59.0 | No | Ramp XSlope (%) | 3.8 |
| Stop Condition-Street 1 | None | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | N/A | Shared Landing? | N/A | | | |
| | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | To NE |
| | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | | | X Walk 1 Slope (%) | 0.4 | | X Walk 2 Slope (%) | 6.3 |
| | | | X Walk 1 X Slope (%) | 5.1 | | X Walk 2 X Slope (%) | 1.4 |
| | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | | | Road Slope (%) | 2.8 | N/A | Clear Space? | N/A |
| | | | Road X Slope (%) | 0.4 | N/A | Clear Space to XWalk (in) | N/A |
| | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | N/A | | | N/A |
| | | | | | Yes | Surface Condition? (G/P) | Good |
| Total Cost: | | \$ 3200.00 | | | | | |

