

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11430	Main Street: ALLEN_ST	Cross Street: GRACE_ST	Location: NE
ADA ID: CB422661FF8D	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 1.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	53.0	Yes	Ramp Slope (%)	8.0
	Surveyor Notes:		No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.4
			Yes	Flare Type L	Curbed_NoWalkSurface	Yes	Flare Type RT	N/A
	N/A		Yes	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
	PROW/ADA:		Yes	Landing Length (in)	51.0	Yes	DWS Provided?	Yes
			No	Landing Width (in)	47.5	Yes	DWS Contrast?	Yes
	R304.5.1, R304.2.1, R304.2.2-Perp, R304.3.2-Para		No	Landing Slope (%)	3.2	Yes	DWS Length (in)	24.0
			Yes	Landing X Slope (%)	0.4	Yes	DWS Full Width?	Yes
			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
			N/A	Shared Landing?	No			
			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.4
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.2
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To E		X Walk 2 Direction	To S
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	0.6
				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	0.3
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	1.4	N/A	Clear Space?	Yes
				Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
Total Cost:		\$ 3200.00				N/A		N/A
						Yes	Surface Condition? (G/P)	Good

