

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 28322Main Street:ARDREY_KELL_RDCross Street:BEAU_RILEY_RDLocation:NWADA ID: CB509CB3851ERamp Type:MedianPerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data Compliance Description



Street 1 Name	BEAU RILEY RD
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/A Ramp Length (in)
Yes Ramp Width (in)
N/A Flare Type LT
N/A Flare Slope LT (%)
N/A Landing Length (in)

Surveyor Notes:
N/A Landing Width (in)
N/A Landing Slope (%)
N/A Landing Slope (%)
N/A Landing Curb? (Y/N
N/A Shared Landing?

PROW/ADA:
N/A Gutter Ponding?
N/A Gutter Lip Ht (in)
N/A Yalk 1 Direction
N/A X Walk 1 Direction
N/A X Walk 1 Slope (%)

Total Cost: \$ 1650.00

N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	14.5
Yes	Ramp Width (in)	58.0	Yes	Ramp XSlope (%)	2.0
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
	. 44				





