

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

53.5

43.0

5.0

0.9

0.6

7.6

N/A

Intersection ID: 42387 Main Street: JAVITZ RD Cross Street: REAMES RD Location: NE **Overall Compliance: No** Severity Score: 46.25 ADA ID: CBB02139E62F Ramp Type: Combination1 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

55.0

43.0

9.8

0.3

51.0

46.0

N/A

No

N/A

0.2

7.0

N/A

N/A

N/A

To SE

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%) X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign JAVITZ RD Stop Condition-Street 1 N/A Street 2 Name Stop Condition-Street 2 N/A

Compliance Description Possible Solutions: N/A Remove & Replace Entire Ramp. No No Yes N/A No Surveyor Notes: N/A **RP < 5%** N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.1, N/A R304.5.3, R304.3.2 N/A N/A N/A N/A N/A





Total Cost:



N/A

1800.00

| N/A | Clear Space to XWalk (in) | N/A |
|-----|-----------------------------|------|
| N/A | Any Obstruction? | N/A |
| | Obstruction Type | |
| | | N/A |
| N/A | Storm Grate/Utility Hazard? | N/A |
| | Storm Grate/Utility Type | |
| | | N/A |
| Yes | Surface Condition? (G/P) | Good |
| | Curb Slope (%) | 19.1 |