cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29768 Main Str	68 Main Street: KNIGHT_CASTLE_DR			WILD_AZALEA_LN	Location:	NW		
ADA ID: CBE704C23A9C Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				21.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
THE ATAMAN IN IS INTICE IN IS INTERED. IN IS INTERED. IN IS INTERED. IN IS INTERED. IN IS INTERED. IN IS IN IS INTERED. IN IS INTERED. IN IS INTERED. INTERED. IN IS INTERED. INTERED. IN IS INTERED.	Possible Solutions:		Compliance Description			Data Compliance Description		Data
	Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	94.0	Yes	Ramp Slope (%)	5.8
			No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	5.6
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
and a second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name WILD AZALEA LN	-			X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	1.7
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	1.1
Street 2 Name KNIGHT CASTLE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	1.0	N/A	Clear Space?	N/A
				Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
				••	N/A			N/A

Yes Surface Condition? (G/P)

Good

