

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                            |                            |                        |
|------------------------|----------------------------|----------------------------|------------------------|
| Intersection ID: 14371 | Main Street: PROVIDENCE_RD | Cross Street: S_CASWELL_RD | Location: S            |
| ADA ID: CC1C1D5B5C81   | Ramp Type: PerpDiag        | Initial Pass/Fail: Fail    | Overall Compliance: No |
|                        |                            |                            | Severity Score: 33.75  |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Restripe Crosswalk.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.5.1, R304.5.3**

Total Cost: \$ 3400.00

| Compliance | Description           | Data  | Compliance | Description                 | Data  |
|------------|-----------------------|-------|------------|-----------------------------|-------|
| N/A        | Ramp Length (in)      | 73.0  | Yes        | Ramp Slope (%)              | 5.9   |
| No         | Ramp Width (in)       | 47.0  | No         | Ramp XSlope (%)             | 7.7   |
| N/A        | Flare Type LT         | N/A   | N/A        | Flare Type RT               | N/A   |
| N/A        | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | N/A   |
| N/A        | Flare Traversable LT? | N/A   | N/A        | Flare Traversable RT?       | N/A   |
| N/A        | Landing Length (in)   | N/A   | N/A        | DWS Provided?               | N/A   |
| N/A        | Landing Width (in)    | N/A   | N/A        | DWS Contrast?               | N/A   |
| N/A        | Landing Slope (%)     | N/A   | N/A        | DWS Length (in)             | N/A   |
| N/A        | Landing X Slope (%)   | N/A   | N/A        | DWS Full Width?             | N/A   |
| N/A        | Landing Curb? (Y/N)   | N/A   | N/A        | DWS Offset (in)             | N/A   |
| N/A        | Shared Landing?       | N/A   |            |                             |       |
| N/A        | Gutter Ponding?       | N/A   | N/A        | Gutter Slope (%)            | N/A   |
| N/A        | Gutter Lip Ht (in)    | N/A   | N/A        | Gutter X Slope (%)          | N/A   |
| N/A        | Painted X Walk1?      | Yes   | N/A        | Painted X Walk2?            | Yes   |
|            | X Walk 1 Direction    | To NE |            | X Walk 2 Direction          | To NW |
| N/A        | X Walk 1 Width (in)   | 116.0 | N/A        | X Walk 2 Width (in)         | 114.0 |
|            | X Walk 1 Slope (%)    | 10.7  |            | X Walk 2 Slope (%)          | 3.5   |
|            | X Walk 1 X Slope (%)  | 2.8   |            | X Walk 2 X Slope (%)        | 11.3  |
| N/A        | Ramp inside XWalk1?   | No    | N/A        | Ramp inside XWalk2?         | Yes   |
|            | Road Slope (%)        | 7.2   | N/A        | Clear Space?                | N/A   |
|            | Road X Slope (%)      | 13.0  | N/A        | Clear Space to XWalk (in)   | N/A   |
| N/A        | Any Obstructions?     | N/A   | N/A        | Storm Grate/Utility Hazard? | N/A   |
|            | Obstruction Type      |       |            | Storm Grate/Utility Type    |       |
|            |                       | N/A   |            |                             | N/A   |
|            |                       |       | Yes        | Surface Condition? (G/P)    | Good  |

Street 1 Name PROVIDENCE RD  
 Stop Condition-Street 2 Signal  
 Street 2 Name S\_CASWELL\_RD  
 Stop Condition-Street 1 Signal

