cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14028	D: 14028 Main Street: ROSS_AV					WEST_BV		Location: SE			
ADA ID: CC33888E6717	Ramp Type: Combination2Diag			Initial	Initial Pass/Fail: Fail Overall Complian				o Severity Score:	0	
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance					
		Possible Solutions:			Comp	Compliance Description		Comp	bliance Description	Data	
	S.M.	Remove & Replace Cur	b Ram	p With	N/A	Ramp Length LT (in)	N/A	N/A	Ramp Length RT (in)	50.0	
when the second of the		Two New Directional Ra			N/A	Ramp Width LT (in)	N/A	No	Ramp Width RT (in)	42.0	
		Equivalent.			N/A	Ramp Slope LT (%)	N/A	No	Ramp Slope RT (%)	10.3	
	A water				N/A	Ramp XSlope LT (%)	N/A	No	Ramp XSlope RT (%)	4.0	
	Alt .				N/A	Ramp Length (in)	43.0	Yes	Ramp Slope (%)	3.3	
					No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	4.2	
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
もしたない	The state of	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
AD PARTY A DECK					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	1217				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	and the second second	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
ALL PROVIDENCE	and the	R304.5.1, R304.5.1, R3	04.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		R304.3.2	•,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	A State Bar				N/A	Shared Landing?	N/A				
A CONTRACTOR OF A CONTRACTOR OFTA CONTRACTOR O			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	WEST BV				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	StopSign					X Walk 1 Direction	To N		X Walk 2 Direction	To W	
Stop Condition-Street 2	ROSS AV					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	3.5	
						X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	1.2	
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			•			Road Slope (%)	3.5		Clear Space?	N/A	
						Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A	
								N/A	Any Obstruction?	N/A	
			A COLOR						Obstruction Type		
Such R.	-					and the second s				N/A	
las the eres			10	1 4		and the second		N/A	Storm Grate/Utility Hazard?		
			-11-		Cart in				Storm Grate/Utility Type	N/A	
						the second se		1		NI/A	

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 1.2





