


Intersection ID: 10034609	Main Street: PLANTATION_CENTER_DR	Cross Street: N/A	Location:	S
ADA ID: CC3D4A428B01	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 13.75

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



### Possible Solutions:

### Remove & Replace Entire Ramp.

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.3.2, R304.5.3**

Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
<b>Remove &amp; Replace Entire Ramp.</b>			N/A	Ramp Length LT (in)	55.0	N/A	Ramp Length RT (in)	54.0
			Yes	Ramp Width LT (in)	97.0	Yes	Ramp Width RT (in)	97.0
			No	Ramp Slope LT (%)	11.2	Yes	Ramp Slope RT (%)	5.7
			No	Ramp XSlope LT (%)	4.3	Yes	Ramp XSlope RT (%)	1.2
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Surveyor Notes:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	<b>N/A</b>		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
PROW/ADA:			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	<b>R304.3.2, R304.5.3</b>		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
				Obstruction Type			Storm Grate/Utility Type	
Total Cost:	\$	1600.00			N/A			N/A
						Yes	Surface Condition? (G/P)	Good
						N/A	Curb Slope (%)	8.5

Total Cost: \$ 1600.00

