

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5314 Main Street: PAVILION BV Cross Street: WHEATSIDE_DR Location: **Overall Compliance: No** ADA ID: CC40C05EE8A4 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



WHEATSIDE DR Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3

Total Cost: 1850.00

Field Measurements/Component Compliance					
Compliance Description		Data	Comp	liance Description	Data
N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	9.5
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.6
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%) N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable I	RT? N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)) N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in) N/A
	X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%) N/A
	X Walk 1 X Slope (%)	4.7		X Walk 2 X Slope ((%) N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWal	k2? N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XW	/alk (in) N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility	Hazard? N/A
	Obstruction Type			Storm Grate/Utility	Туре
		N/A			N/A
			Yes	Surface Condition?	(G/P) Good





