## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · · · · · · · · · · · · · · ·									
Intersection ID: 30269	Main Street: ARROLL_CT		Cross	Cross Street: FORTESCUE_DR				Location:	NW
ADA ID: CC93A7A6DC70	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description D			ta Compliance Description		Data
		Remove & Replace Curb Rar	nn With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	3.6
		Two New Directional Ramps	•	Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	11.0
		Equivalent.	-	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	he and the	Surveyor Notes:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Ros	12			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A State A		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E State				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		A		N/A	Shared Landing?	N/A	N/A	DWS Oliset (III)	IN/A
				N/A	Gutter Ponding?		N/A	Cuttor Clana (0/)	N/A
A AR		PROW/ADA:			0	N/A		Gutter Slope (%)	
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To SE
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	RTESCUE DR				X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	4.5
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	7.1		X Walk 2 X Slope (%)	6.4
Street 2 Name	ARROLL CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	9.4		Clear Space?	N/A
					Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

16.1