cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28695	ion ID: 28695 Main Street: OLD_LITTLE_ROCK_RD				Cross Street: WESBROOK_DR				N/A
ADA ID: CCE6FB0BB7E2	D: CCE6FB0BB7E2 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Da			a Compliance Description Data		
		Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	25.0	Yes	Ramp Slope (%)	6.3
	1 1 200		•	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	3.4
		•		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	11111			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A TRA			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
WESEROOK DR 6. T	RE	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second second	A Cash -			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	I tale to the second			N/A	Shared Landing?	N/A			
Star The August 7	11/2 PAR	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
All a start and a start and a start and a start	A second second	Not Found, R304.5.1, R304.5	5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
NAGE V	Comment.	,,,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
A A A A A A A A A A A A A A A A A A A	A State of the				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	1 CELIA			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	WESTBROOK DR	_			X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	3.1	N/A	Clear Space?	N/A
					Road X Slope (%)	2.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good





