


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12322	Main Street: HIGHLAND_ST	Cross Street: GREENLAND_AV	Location: NW
ADA ID: CD11B4A76483	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

		Possible Solutions:		Compliance		Description		Data	Compliance	Description	Data
		Remove & Replace Entire Ramp.		N/A		Ramp Length LT (in)		57.5	N/A	Ramp Length RT (in)	56.0
				Yes		Ramp Width LT (in)		60.0	Yes	Ramp Width RT (in)	60.5
				No		Ramp Slope LT (%)		11.1	Yes	Ramp Slope RT (%)	1.9
				No		Ramp XSlope LT (%)		3.1	No	Ramp XSlope RT (%)	2.6
				N/A		Landing Length (in)		N/A	N/A	DWS Provided?	N/A
				N/A		Landing Width (in)		N/A	N/A	DWS Contrast?	N/A
				N/A		Landing Slope (%)		N/A	N/A	DWS Length (in)	N/A
				N/A		Landing X Slope (%)		N/A	N/A	DWS Full Width?	N/A
				N/A		Landing Curb? (Y/N)		N/A	N/A	DWS Offset (in)	N/A
				N/A		Shared Landing?		N/A			
				N/A		Gutter Ponding?		N/A	N/A	Gutter Slope (%)	N/A
				N/A		Gutter Lip Ht (in)		N/A	N/A	Gutter X Slope (%)	N/A
				N/A		Painted X Walk1?		No	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction		To E		X Walk 2 Direction	N/A
				N/A		X Walk 1 Width (in)		N/A	N/A	X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)		1.4		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)		2.8		X Walk 2 X Slope (%)	N/A
				N/A		Ramp inside XWalk1?		N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)		N/A	N/A	Clear Space?	N/A
						Road X Slope (%)		N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A		Any Obstructions?		N/A	N/A	Storm Grate/Utility Hazard?	N/A
						Obstruction Type				Storm Grate/Utility Type	
								N/A			N/A
									Yes	Surface Condition? (G/P)	Good
									N/A	Curb Slope (%)	17.1

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

R304.3.2, R304.5.3

Total Cost:

\$ 1600.00

