

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24836	Main Str	reet: PARK_CROSSING_DR Cross Street: WELWYN_LN					Location:	SE	
ADA ID: CD3ABBFEE775 Ramp Ty		/pe: PerpDiag	Initial Pa	nitial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	34.0	No	Ramp Slope (%)	10.4
A A A A A A A A A A A A A A A A A A A		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.0
State 12 Martin				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	and the second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A CARLEN AND A CARLEN				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To W
THE REAL PROPERTY AND				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	WELWYN LN	-			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	4.4
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	0.9
Street 2 Name PA	RK CROSSING DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.2	N/A	Clear Space?	N/A
					Road X Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

