

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24614 Main Street: BECKMORE_PL				Cross	Street:	PINEVILLE-MATTHE	Location:	SE		
ADA ID: CD3B12CEC	CA24 Ramp T	4 Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian				nce: No Severity Score:	
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance										
THE PART OF THE		Possible Solutions:			Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb	Ramp	With	N/A	Ramp Length LT (in)	39.5	N/A	Ramp Length RT (in)	41.0
		Two New Directional Rar			No	Ramp Width LT (in)	47.0	No	Ramp Width RT (in)	47.0
6 6 6	TEVEL	Equivalent.			Yes	Ramp Slope LT (%)	8.3	Yes	Ramp Slope RT (%)	0.8
<u>a</u>	ALEADAY WWW.	5			Yes	Ramp XSlope LT (%)	1.5	Yes	Ramp XSlope RT (%)	1.1
	All				N/A	Ramp Length (in)	24.0	Yes	Ramp Slope (%)	6.8
G		9			No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	3.6
	and a start	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	L	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
t.	The stand				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
1 Station		1			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 1000	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Tes Balling	1	Not Found, R304.5.1, R3	804.5.1,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
O. P. Car	Colorador I	R304.5.3			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	L L LEELS A	e 4			N/A	Shared Landing?	N/A			
	R CARE A				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	PINEVILLE-MATTHEWS RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign					X Walk 1 Direction	To N		X Walk 2 Direction	To W
Stop Condition-Street 2	BECKMORE PL					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	1.4
						X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	3.1
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	3.1		Clear Space?	N/A
						Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
				STATE		- States		N/A	Any Obstruction?	N/A
	and the second sec	+	And and the	Constant of the					Obstruction Type	
										N/A
LEEMISTE AD								N/A	Storm Grate/Utility Hazard?	N/A
									Storm Grate/Utility Type	
	1				~					N/A
					11/			Yes	Surface Condition? (G/P)	Good
1-t-			AN		1	1		I	Curb Slope (%)	12.0