


Intersection ID: 12384	Main Street: FRIAR_ST	Cross Street: PRUITT_ST	Location:	SE
ADA ID: CD6F26A27814	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance									
	Possible Solutions:		Compliance			Description			Data			
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		50.0		No	Ramp Slope (%)		15.3	
			Yes	Ramp Width (in)		50.0		Yes	Ramp XSlope (%)		0.8	
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A	
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		N/A	
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A	
			N/A	Landing Length (in)		N/A		N/A	DWS Provided?		N/A	
			N/A	Landing Width (in)		N/A		N/A	DWS Contrast?		N/A	
			N/A	Landing Slope (%)		N/A		N/A	DWS Length (in)		N/A	
			N/A	Landing X Slope (%)		N/A		N/A	DWS Full Width?		N/A	
Surveyor Notes:			N/A	Landing Curb? (Y/N)		N/A		N/A	DWS Offset (in)		N/A	
N/A			N/A	Shared Landing?		N/A						
PROW/ADA:			N/A	Gutter Ponding?		N/A		N/A	Gutter Slope (%)		N/A	
Not Found, R304.2.2			N/A	Gutter Lip Ht (in)		N/A		N/A	Gutter X Slope (%)		N/A	
			N/A	Painted X Walk1?		No		N/A	Painted X Walk2?		N/A	
				X Walk 1 Direction		To N			X Walk 2 Direction		N/A	
			N/A	X Walk 1 Width (in)		N/A		N/A	X Walk 2 Width (in)		N/A	
				X Walk 1 Slope (%)		0.8			X Walk 2 Slope (%)		N/A	
				X Walk 1 X Slope (%)		5.0			X Walk 2 X Slope (%)		N/A	
Street 1 Name		FRIAR ST	N/A	Ramp inside XWalk1?		N/A		N/A	Ramp inside XWalk2?		N/A	
Stop Condition-Street 2		StopSign		Road Slope (%)		4.0		N/A	Clear Space?		N/A	
Street 2 Name		N/A		Road X Slope (%)		0.1		N/A	Clear Space to XWalk (in)		N/A	
Stop Condition-Street 1		N/A		N/A	N/A		N/A	Storm Grate/Utility Hazard?		N/A		
Total Cost:			\$	1850.00					Storm Grate/Utility Type			
						N/A					N/A	
								Yes	Surface Condition? (G/P)		Good	

