## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48946	Main Str	eet: DAVID_JENNIN	GS_AV C	Cross Street: MITCHELL_GRANT_WY				Location:	SW
ADA ID: CDAB1A66A02A	Ramp Ty	Ramp Type: Combination2			ail: Fail Overall (	ce: N	o Severity Score:	22.5	
Codes	Mitigation Info	Possible Solution			Field Measure	ements/Co	ompo	nent Compliance	
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
	2/1	Remove & Replac	e Entire Ramp.	N/A	Ramp Length LT (in)	9.0	N/A	Ramp Length RT (in)	14.0
				Yes	Ramp Width LT (in)	60.0	N/A	Ramp Width RT (in)	59.0
				No	Ramp Slope LT (%)	8.4	N/A	Ramp Slope RT (%)	4.4
and here				No	Ramp XSlope LT (%)	3.4	N/A	Ramp XSlope RT (%)	1.5
	11/2			N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	4.8
the state	19/ 1			No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	2.0
	16 3	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1. 3 MAY 10 1	RT RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the second secon	1			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ALL				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	18			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	0	PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ALL A	1.00	Not Found, R304.	5.1, R304.3.2,	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		R304.5.3		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	And the second			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1 DAV	ID JENNINGS AV			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	N/A
					X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 1600.	.00 N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	N/A		Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					and the second second		N/A	Any Obstruction?	N/A
	- L							Obstruction Type	
		to provide the second s							N/A

- N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A
- Yes
   Surface Condition? (G/P)
   Good

   Curb Slope (%)
   18.2



