

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49347 Main St		reet: BLUE_JUNCTION_RD	Cross	Street:	BRYANT_FARMS_RD			Location:	NE
		Type: Perp		Initial Pass/Fail: Fail Overall Compliance			nce: N		10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:								liance Description	Data
	1 Alexandream Providence	Remove & Replace Entire Ram	n	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	8.0
			μ.	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	4.0
	THE REPORT OF THE THE REPORT OF THE REPORT O			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		1		N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		6		N/A	Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
<mark>ત્ર</mark>		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second	BRYANT FARMS RD			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Contraction of the second				N/A	Shared Landing?	N/A			
	The second second second	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
THE PARTY AND A MARKED		á.		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
	and the second	Not Found, R304.5.1, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	The sec	9 1		N/A	X Walk 1 Direction	To W		X Walk 2 Direction	N/A
and the second second second second				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A N/A
Church 4 Manua	BLUE JUNCTION RD			N/A			N/A	. ,	
Street 1 Name					X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

