


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|---------------------------|---------------------------------------|-------------------------|------------------------|
| Intersection ID: 10033070 | Main Street: NORTH_COMMUNITY_HOUSE_RD | Cross Street: N/A | Location: NE |
| ADA ID: CDF1215B4830 | Ramp Type: Perp | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | Severity Score: 8.75 | |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | |
|--|--|------------|---|-----------------------------|-------------|
|  | Possible Solutions: | | Compliance | Description | Data |
| | Remove & Replace Entire Ramp. | | Yes | Ramp Length (in) | 56.0 |
| | | | No | Ramp Width (in) | 37.5 |
| | | | N/A | Flare Type LT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A |
| | | | N/A | Flare Traversable RT? | N/A |
| | | | N/A | DWS Provided? | N/A |
| | | | N/A | DWS Contrast? | N/A |
| | | | N/A | DWS Length (in) | N/A |
| | | | N/A | DWS Full Width? | N/A |
| | | | N/A | DWS Offset (in) | N/A |
| | | | N/A | Gutter Ponding? | N/A |
| | | | N/A | Gutter Lip Ht (in) | N/A |
| | | | No | Painted X Walk1? | N/A |
| | | | To SE | X Walk 2 Direction | N/A |
| | | | N/A | X Walk 2 Width (in) | N/A |
| | | | 2.0 | X Walk 2 Slope (%) | N/A |
| | | | 0.8 | X Walk 2 X Slope (%) | N/A |
| | | | N/A | Ramp inside XWalk2? | N/A |
| | | | N/A | Clear Space? | N/A |
| | | | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | N/A | Storm Grate/Utility Type | N/A |
| | | | N/A | Surface Condition? (G/P) | Good |
| Surveyor Notes: | | | | | |
| N/A | | | | | |
| PROW/ADA: | | | | | |
| Not Found, R304.5.1 | | | | | |
| Total Cost: | | \$ 1850.00 | | | |

| | |
|-------------------------|----------|
| Street 1 Name | ENTRANCE |
| Stop Condition-Street 2 | StopSign |
| Street 2 Name | N/A |
| Stop Condition-Street 1 | N/A |

