

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 42965	ntersection ID: 42965 Main Street: RED_ROBIN_ST		Cross	Street:	QUAIL_ST	Location:	NW		
ADA ID: CE5BBCB3CC8E Ramp Type: PerpDiag		Initial F	Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	10.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	PI	Possible Solutions:		Compliance Description D			Comp	Data	
RED ROCEN DT - LA ST	5	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	7.7
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.3
				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
		-		N/A	Flare Slope LT (%)	6.4	Yes	Flare Slope RT (%)	3.2
				N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
				Yes	Landing Length (in)	48.0	No	DWS Provided?	No
		Surveyor Notes:		Yes	Landing Width (in)	48.0	N/A	DWS Contrast?	No
		N/A		Yes	Landing Slope (%)	1.4	N/A	DWS Length (in)	N/A
				No	Landing X Slope (%)	3.8	N/A	DWS Full Width?	No
the terms				N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	No			
A CAME I FARM		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.6
		Not Found, R304.5.3, R305		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.3
The West of the second		,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
the bar of the second					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
	and the second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RED ROBIN ST				X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	0.9
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	1.6
Street 2 Name	QUAIL ST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.7	N/A	Clear Space?	Yes
					Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

