

# Access Compliance Report


## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 16578	Main Street: CONWAY_AV	Cross Street: SCALEYBARK_RD	Location: S
ADA ID: CED98895D11B	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 7.5	

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Grind Gutter Lip.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R302.7.2**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	41.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	61.0	Yes	Grade Break Slope (%)	2.9
Yes	Ramp Slope (%)	5.0	Yes	Grade Break XSlope (%)	1.7
Yes	Ramp XSlope (%)	2.0			
Yes	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	Yes	Flare Slope RT (%)	6.8
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes
Yes	Landing Length (in)	58.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	68.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.3	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.4	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	25.0
N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	0.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.7
No	Gutter Lip Ht (in)	0.5	Yes	Gutter X Slope (%)	1.4
N/A	Painted X Walk1?	No		Road Slope (%)	3.2
	X Walk 1 Direction	To NE		Road X Slope (%)	1.8
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.8	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	3.0

Total Cost: \$ 200.00

